



NO LIQUIDS



230 V/50 Hz



DOMESTIC USE



375x155x80 h



mm 310



Q= 16 LTmin



impulso - impulse



kg 2



KW 0,25



SENSORE DI VUOTO

Rileva il vuoto totale e passa direttamente alla fase di saldatura

Vacuum sensor: detects the total vacuum and goes directly to the sealing phase

Capteur du vide: détecte le vide total et passe directement à la phase de soudure

Sensor de vacío: mide el vacío total y pasa de manera automática al sellado

CUTTER ESTRAIBILE

Cutter per l'utilizzo di sacchetti in rotoli

Cutter for bags in rolls

Cutter pour l'usage de sachets en rouleau

Cuchillo para el uso de bolsas en rollos

VUOTO IN CONTENITORI

Possibilità di fare il vuoto in appositi contenitori

Possibility to do vacuum in appropriate containers

Possibilité de faire le vide dans des bocaux appropriés

Posibilidad de hacer el vacío en vasos especiales